

APPENDIX C
PHOTOGRAPHS



Photo 1 – View south. Gate at western terminus of LPV 111.



Photo 2 – View west. LPV 111 Floodwall north side.



Photo 3 – View west. LPV 111 Floodwall south side.



Photo 4 – View north. 55-gallon drum and buckets containing tar.



Photo 5 – View north. Empty lubricant drums and Port-A-John at southeast corner of BOC Gases.



Photo 6 –View south. Entergy/Southern Natural Gas pumping station. Levee LPV 111 is in the background.



Photo 7 – Canal Pump House No. 1 near center of LPV 111. Apparently discarded filters and minor surface staining.



Photo 8 – Lead acid batteries apparently abandoned outside Canal Pump House No. 1 near center of LPV 111.



Photo 9 – Several drums labeled for storage of diesel and lubricants, lawn mowers, string trimmers inside Canal Pump House No. 1 near center of LPV 111.



Photo 10 – Open drums labeled for storage of lubricants inside Canal Pump House No. 1 near center of LPV 111.



Photo 11 – Drums and smaller containers labeled for storage of gasoline, diesel and lubricants, lawn mowers, string trimmers inside Canal Pump House No. 1 near center of LPV 111.